

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE**

NUMBER: M5-6MR-8003-X

SUBSYSTEM NAME: ORBITER DOCKING SYSTEM

REVISION: 0 OCT, 1995

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	ENERGIA POWER PANEL RSC-E	MC621-0087-0009 CKB-468-312-001
SRU	PUSH-BUTTON SWITCH	PKZ-8 (AGO.360.212.TU)

**PART DATA****EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:**

PUSH-BUTTON SWITCHES (TWO DOUBLE POLE SWITCHES UNDER A SINGLE COVER CAP.) TWO POLE, MOMENTARY - APDS "POWER-OFF" COMMAND.

REFERENCE DESIGNATORS: 36V73A8A3SB1-B3  
36V73A8A3SB1-B4

QUANTITY OF LIKE ITEMS: 2  
(TWO)

**FUNCTION:**

PROVIDE THE "POWER-OFF" COMMAND TO THE POWER SWITCHING UNIT (PSU.) THE PSU PROVIDES THE LOGIC BUSES TO THE DSCU, DMCU, PACU, AND THE LACU. THESE LOGIC BUSES ARE REQUIRED TO IMPLEMENT ALL DOCKING AND UNDOCKING OPERATIONS.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE**

NUMBER: M5-SMR-B003-02

REVISION# 0 OCT, 1995

SUBSYSTEM NAME: ORBITER DOCKING SYSTEM

LRU: MC621-0087-0009

ITEM NAME: PUSH BUTTON SWITCH

CRITICALITY OF THIS  
FAILURE MODE: 1R3**FAILURE MODE:**

FAILS CLOSED (MULTIPLE CONTACTS WITHIN ONE SWITCH,) SHORTS TO GROUND

**MISSION PHASE:**

OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 104 ATLANTIS

**CAUSE:**A) PIECE PART FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E)  
PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

**REDUNDANCY SCREEN**

A) PASS

B) PASS

C) PASS

**PASS/FAIL RATIONALE:**

A)

B)

C)

**METHOD OF FAULT DETECTION:**

THE STATUS OF THE APDS SYSTEM BUSES IS DISPLAYED ON THE PANEL.

**MASTER MEAS. LIST NUMBERS:**

V53X0785E

**CORRECTING ACTION:**

NONE

**- FAILURE EFFECTS -****(A) SUBSYSTEM:**

LOSS OF SWITCH CONTROL CAPABILITY FOR THE APDS "POWER-OFF" COMMAND.

**(B) INTERFACING SUBSYSTEM(S):**

UNWANTED "POWER OFF" COMMAND TO THE PSU.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE  
NUMBER: M5-6MR-8003-02**

**(C) MISSION:**  
NO EFFECT.

**(D) CREW, VEHICLE, AND ELEMENT(S):**  
FIRST FAILURE - NO EFFECT.

**(E) FUNCTIONAL CRITICALITY EFFECTS:**  
POSSIBLE LOSS OF CREW OR VEHICLE AFTER FOUR FAILURES. 1) ONE OF TWO ASSOCIATED SWITCHES FAILS CLOSED (MULTIPLE CONTACTS) DURING THE AUTOMATIC DOCKING SEQUENCE (AFTER CAPTURE BUT PRIOR TO HOOKS ENGAGED.) ENABLES TWO OF THREE COMMAND CHANNELS. UNWANTED "POWER OFF" COMMAND TO THE PSU. TEMPORARY LOSS OF CAPABILITY TO COMPLETE DOCKING AND OPEN CAPTURE LATCHES TO SEPARATE. CREW WOULD PERFORM AN APDS LOGIC BUS DROP TO RECOVER DOCKING FUNCTIONS.

**DESIGN CRITICALITY (PRIOR TO OPERATIONAL DOWNGRADE, DESCRIBED IN F): 1R2**

**(F) RATIONALE FOR CRITICALITY CATEGORY DOWNGRADE:**  
SECOND FAILURE (INABILITY TO DISABLE AFFECTED APDS LOGIC BUS) - LOSS OF CAPABILITY TO RECOVER FUNCTION.  
THIRD FAILURE (INABILITY TO PERFORM IFM TO DRIVE THE CAPTURE LATCHES OPEN) - LOSS OF CAPABILITY TO SEPARATE.  
FOURTH FAILURE (FAILURE OF EVA TO REMOVE 96 BOLTS) - LOSS OF ALL UNDOCKING CAPABILITY.

---

**- TIME FRAME -**

---

**TIME FROM FAILURE TO CRITICAL EFFECT: DAYS**  
**TIME FROM FAILURE OCCURRENCE TO DETECTION: MINUTES**  
**TIME FROM DETECTION TO COMPLETED CORRECTIVE ACTION: HOURS**  
**TIME REQUIRED TO IMPLEMENT CORRECTIVE ACTION LESS THAN TIME TO EFFECT?**  
YES

**RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:**  
CREW WOULD HAVE SUFFICIENT TIME TO PERFORM 96 BOLT EVA OR DISABLE AFFECTED BUS.

**HAZARDS REPORT NUMBER(S): ORBI 401A**

**HAZARD DESCRIPTION:**  
INABILITY TO SEPARATE ORBITER AND MIR.

---

**- APPROVALS -**

---

**PRODUCT ASSURANCE ENGR**

: M. NIKOLAYEVA

**DESIGN ENGINEER**

: B. VAKULIN